

Aerojet Quality Note**G21****Rev #****Date****0****11/5/08**

The seller shall report to Aerojet buyer the failure of any Aerojet required test (e.g., functional test, leak test, vibration test, burst test, etc.) Hardware experiencing a test failure shall be maintained in its same condition pending authorization from Aerojet for any investigation activity (i.e., do not disassemble, do not retest). The following notification schedule applies:

- Within 24 hours: Report by telephone
- Within 5 days: A preliminary written report.
- Within 30 days: A final written failure analysis report identifying failure cause and action(s) taken to prevent recurrence.

For those items under design cognizance of the seller, Aerojet shall approve the failure analysis investigation plan and may participate in investigation.

Items for which the seller does not have design cognizance (e.g. build to print), require Aerojet's approval of failure investigation results and remedial actions prior to resumption of production/testing.

Rev	Date	Description of Change	Changed By

This document is an integral part of the contract (purchase order) in which referenced. **Applicable Revision:** The revision in effect at the time the purchase order is placed.